




CPH30

Transom Patch with Pivot



Glass cutting-out